


CHAPA PERFORADA

AGUJEROS REDONDOS

2500x1250mm




| | | Fe | | | | G | | |
|----|----|----|-----|---|---|---|-----|---|
| | | I | | | | | | |
| R | T | 1 | 1,5 | 2 | 3 | 1 | 1,5 | 2 |
| 3 | 5 | ● | ● | ● | | | | |
| 5 | 7 | | ● | | | ● | ● | |
| 5 | 8 | | ● | ● | | | ● | |
| 6 | 10 | | | ● | | | | |
| 8 | 11 | | ● | | | | | |
| 8 | 12 | | | ● | | | | |
| 10 | 14 | | ● | | | | ● | |
| 10 | 15 | | | ● | ● | | | ● |
| 20 | 27 | | | ● | | | | |

3000x1500mm

| | | Fe | | G | |
|----|-----|-----|---|-----|---|
| | | I | | | |
| R | T | 1,5 | 2 | 1,5 | 2 |
| 3 | 5 | ● | ● | ● | ● |
| 4 | 6 | ● | | ● | |
| 4 | 7 | | ● | | |
| 5 | 7 | ● | | ● | |
| 5 | 8 | | ● | | ● |
| 6 | 8,5 | ● | | ● | |
| 6 | 10 | | ● | | ● |
| 8 | 11 | ● | | ● | |
| 8 | 12 | | ● | | ● |
| 10 | 14 | ● | | ● | |
| 10 | 15 | | ● | | ● |
| 20 | 27 | | ● | | |

CHAPA PERFORADA

AGUJEROS CUADRADOS




2000x1000mm

| | | Fe | | | | G | | I A304L |
|----|-----|----|-----|---|---|-----|---|---------|
| | | I | | | | | | |
| C | U | 1 | 1,5 | 2 | 3 | 1,5 | 2 | 1,5 |
| 3 | 5 | ● | | | | | | |
| 5 | 7,5 | ● | | | | | | |
| 5 | 8 | ● | ● | ● | | | | |
| 8 | 11 | ● | ● | ● | | | | |
| 8 | 12 | | ● | ● | | | | |
| 10 | 12 | ● | ● | | | | | |
| 10 | 13 | ● | ● | ● | | | | |
| 10 | 15 | ● | ● | ● | ● | ● | ● | ● |
| 10 | 20 | ● | ● | ● | | ● | ● | |
| 15 | 20 | ● | ● | ● | ● | | | |
| 15 | 30 | | ● | ● | | | | |
| 20 | 25 | | ● | ● | ● | | | |
| 20 | 40 | ● | ● | ● | ● | ● | ● | ● |
| 25 | 50 | | ● | ● | | | | |
| 30 | 35 | | | ● | | | | |
| 30 | 60 | ● | ● | ● | ● | ● | ● | |
| 40 | 50 | | ● | ● | ● | | | |
| 40 | 80 | ● | ● | ● | ● | ● | ● | |
| 50 | 100 | | ● | ● | ● | ● | | |

CHAPA PERFORADA

AGUJEROS CUADRADOS

2500x1250mm



| | | Fe | |
|----|----|-----|---|
| | | I | |
| C | U | 1,5 | 2 |
| 10 | 15 | ● | ● |

3000x1500mm

| | | Fe | | G | |
|----|----|-----|---|-----|---|
| | | I | | | |
| C | U | 1,5 | 2 | 1,5 | 2 |
| 10 | 15 | ● | ● | ● | ● |
| 10 | 20 | ● | ● | ● | |
| 20 | 40 | ● | ● | ● | ● |
| 30 | 60 | ● | ● | ● | ● |
| 40 | 80 | ● | ● | ● | ● |


CHAPA PERFORADA

AGUJEROS LARGOS REDONDOS


2000x1000mm

| | Fe | | |
|------------------|----|-----|---|
| | I | | |
| | 1 | 1,5 | 2 |
| LR2x20Z10x25I | | • | • |
| LR3x20U6x26II | • | | |
| LR4x20U8x25II | • | | |
| LR4x20Z16x25I | | • | • |
| LR5x20U10x25II | | • | |
| LR5x20Z20x25I | | • | • |
| LR6x20U11x25II | • | | |
| LR8x40U13x47,5II | | • | |


LR Z I




LR Z II



LR U I



LR U II




CHAPA PERFORADA


CHAPA DECORATIVA

2000x1000mm

| | Fe | | |
|------|-----|---|-----|
| | I | | |
| | 0,8 | 1 | 1,5 |
| D501 | ● | ● | ● |
| D504 | | | ● |
| D505 | ● | ● | ● |
| D508 | | ● | |
| D513 | ● | ● | ● |
| D561 | ● | ● | ● |




D501



D504



D505



D508



D513



D561

CHAPA PERFORADA

CHAPA DECORATIVA CUADRADA

2000x1000mm

| | | Fe | | G |
|----|----|-----|---|-----|
| | | I | | |
| C | U | 1,5 | 2 | 1,5 |
| 20 | 40 | ● | | ● |
| 30 | 50 | ● | | |
| 40 | 60 | ● | | |

